



[Lawrence Berkeley National Laboratory](#)

Title:

Erratic Dislocations within Funnel Defects in AlN Templates for AlGaN Epitaxial Layer Growth

Author:

[Hawkridge, Michael E](#)

Publication Date:

05-21-2009

Publication Info:

Lawrence Berkeley National Laboratory

Permalink:

<http://www.escholarship.org/uc/item/12w066c3>

Citation:

Hawkridge, Michael E. (2009). Erratic Dislocations within Funnel Defects in AlN Templates for AlGaN Epitaxial Layer Growth . Lawrence Berkeley National Laboratory: Lawrence Berkeley National Laboratory. LBNL Paper LBNL-1792E. Retrieved from: <http://www.escholarship.org/uc/item/12w066c3>

Keywords:

AlN Templates, Phase Separation, Dislocations, TEM

Abstract:

We report our transmission electron microscopy observations of erratic dislocation behavior within funnel-like defects in the top of AlN templates filled with AlGaN from an overlying epitaxial layer. This dislocation behavior is observed in material where phase separation is also observed. Several bare AlN templates were examined to determine the formation mechanism of the funnels. Our results suggest that they are formed prior to epitaxial layer deposition due to the presence of impurities during template re-growth. We discuss the erratic dislocation behavior in relation to the presence of the phase-separated material and the possible effects of these defects on the optoelectronic properties.



eScholarship
University of California

eScholarship provides open access, scholarly publishing services to the University of California and delivers a dynamic research platform to scholars worldwide.

Report Documentation Page			Form Approved OMB No. 0704-0188	
<p>Public reporting burden for the collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to a penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number.</p>				
1. REPORT DATE 21 MAY 2009	2. REPORT TYPE	3. DATES COVERED 00-00-2009 to 00-00-2009		
4. TITLE AND SUBTITLE Erratic Dislocations within Funnel Defects in AlN Templates for AlGaN Epitaxial Layer Growth			5a. CONTRACT NUMBER	
			5b. GRANT NUMBER	
			5c. PROGRAM ELEMENT NUMBER	
6. AUTHOR(S)			5d. PROJECT NUMBER	
			5e. TASK NUMBER	
			5f. WORK UNIT NUMBER	
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) Materials Science Division, Lawrence Berkeley National Laboratory,1 Cyclotron Road,MS 62R0209/213,Berkeley,CA,94720			8. PERFORMING ORGANIZATION REPORT NUMBER	
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)			10. SPONSOR/MONITOR'S ACRONYM(S)	
			11. SPONSOR/MONITOR'S REPORT NUMBER(S)	
12. DISTRIBUTION/AVAILABILITY STATEMENT Approved for public release; distribution unlimited				
13. SUPPLEMENTARY NOTES				
14. ABSTRACT				
15. SUBJECT TERMS				
16. SECURITY CLASSIFICATION OF: a. REPORT b. ABSTRACT c. THIS PAGE unclassified unclassified unclassified			17. LIMITATION OF ABSTRACT Same as Report (SAR)	18. NUMBER OF PAGES 16
				19a. NAME OF RESPONSIBLE PERSON

Erratic Dislocations within Funnel Defects in AlN Templates for AlGaN Epitaxial Layer Growth

M. E. Hawkridge^{1, a)}, Z. Liliental-Weber¹, H. J. Kim², S. Choi², D. Yoo², J. -H. Ryou², and R. D. Dupuis²

¹ Materials Science Division, Lawrence Berkeley National Laboratory, 1 Cyclotron Road MS 62R0209/213, Berkeley, CA 94720, USA

² Center for Compound Semiconductors and School of Electrical and Computer Engineering, Georgia Institute of Technology, 777 Atlantic Dr. NW, Atlanta, Georgia 30332-0250, USA

Abstract

We report our transmission electron microscopy observations of erratic dislocation behavior within funnel-like defects in the top of AlN templates filled with AlGaN from an overlying epitaxial layer. This dislocation behavior is observed in material where phase separation is also observed. Several bare AlN templates were examined to determine the formation mechanism of the funnels. Our results suggest that they are formed prior to epitaxial layer deposition due to the presence of impurities during template re-growth. We discuss the erratic dislocation behavior in relation to the

presence of the phase-separated material and the possible effects of these defects on the optoelectronic properties.

a) Author to whom correspondence should be addressed. Electronic mail:
mehawkridge@lbl.gov

Alloys of AlGaN are of great interest for optoelectronic devices that operate in the UV region of the electromagnetic spectrum due to their direct tunable band gaps in this energy range¹. High Al-content alloys are of particular interest for deep-UV applications such as light emitting diodes (LEDs), photodetectors, and bio-purification². Due to the relative lack of native substrates, these alloys are usually grown by heteroepitaxial techniques on substrates such as sapphire, which introduces high densities of defects and strain into the epitaxial layer detrimental to the final quality. This mismatch can be relieved somewhat by employing a thick template material such as GaN, but growth of Al-rich alloys on GaN introduces significant tensile strain into the layer that can cause cracking³. AlN templates are therefore preferred for Al-rich AlGaN alloys and have been utilized recently to grow high-quality UV-LED structures⁴. As AlN templates become commercially available, they will see greater use for such devices. However, the preparation and quality of the AlN template is critical to obtaining high quality epitaxial layers and is often glossed over in the drive to obtain working devices.

In addition to the issues surrounding heteroepitaxy, growth of high Al content AlGaN alloys by conventional metalorganic chemical vapor deposition (MOCVD) is hindered by the high sticking coefficient of Al compared to Ga adatoms and a parasitic gas-phase reaction of TMAl and ammonia^{2,5}. One of the growth methods available for AlGaN that avoids the need for high growth temperatures⁶⁻⁸ is the modulated precursor epitaxial growth (MPEG). In this growth scheme, the group III and V precursors are introduced into the growth chamber separately in an alternating sequence, reducing the parasitic gas-phase reactions and increasing the adatom migration^{9,10}.

In this paper, we report our transmission electron microscopy (TEM) observations of unusual funnel-like defects and erratic dislocations in the surface of AlN templates used for $\text{Al}_x\text{Ga}_{1-x}\text{N}$ growth by MPECVD. Further analysis of conventionally grown bare AlN templates indicates that the funnels are pre-existing hollow defects filled in by the epitaxial material. We discuss the possible formation mechanisms for these funnels and the associated dislocation behavior.

AlN templates were grown on (0001) sapphire substrates using a typical two-step growth of heteroepitaxy employing a low-temperature AlN buffer layer by conventional metalorganic vapor phase epitaxy (MOCVD) to a thickness of around 1 μm . The total dislocation density for the templates was considered to be high (estimated to be on the order of 10^9 cm^{-2} of magnitude), while the surface was confirmed to be free of nanopits (or V-defects) by atomic force microscopy (AFM). $\text{Al}_x\text{Ga}_{1-x}\text{N}$ layers of varying composition ($0.6 < x < 1.0$) were grown on these templates by MOCVD in the MPECVD regime following a brief period (~200nm) of conventional AlN template re-growth. The composition of the AlGaN layer was controlled by the ratio of the precursors used in the group-III stage of growth (further details are provided in Ref. 10). Cross-sectional TEM specimens were prepared using standard polishing and ion milling techniques. Conventional TEM images were obtained using a JEOL 3010 TEM and Z-contrast TEM images were obtained using a Philips G2 Tecnai operating at 200kV.

Standard TEM characterization of several AlGaN layers showed that the layer qualities were very good in general. The samples with higher ($x > 0.75$) aluminum content had smooth surfaces and good crystal perfection indicated by selected area diffraction. In most cases, the interface with the template was observed to be uniformly

smooth and threading dislocations in the template propagated into the epitaxial layer with minimal interaction. However, some samples exhibited unusual defects in the surface of the template and less than ideal $\text{Al}_x\text{Ga}_{1-x}\text{N}$ layer qualities for $x < 0.75$.

Fig. 1 shows bright field TEM images of the epitaxial $\text{Al}_x\text{Ga}_{1-x}\text{N}$ layer in a sample with $x \sim 0.6$. The surface of the AlGaN layer is relatively rough, with approximately $\pm 20\text{nm}$ thickness variation throughout the sample. In the image taken under $\mathbf{g} = (0006)$ conditions [Fig. 1(a)], dislocations with a screw component are observed to thread through the template and into the AlGaN layer well aligned with the [0001] direction. This is considered typical dislocation behavior for epitaxial layer growth. However, some of the dislocations appear to have a highly erratic path close to the interface with the epitaxial layer in the upper $\sim 150\text{nm}$ of the template. The almost helical path in some cases is very unusual, as this orientation does not minimize the line tension of the dislocation. When compared to an image taken under kinematical diffraction imaging conditions [Fig. 1(b)], i.e. away from any strongly diffracting Bragg reflection such that mass-thickness is the dominant contrast mechanism, it becomes apparent that the erratic dislocation behavior occurs within the boundaries of funnel-shaped defects in the template layer. The funnels in Fig. 1(b) appear darker than the surrounding AlN material, suggesting that they are filled with material from the overlying AlGaN layer (containing elements with higher atomic number Z).

The filling of the funnels is more clearly shown in high angle annular dark field (z-contrast) in Fig. 2. It may also be seen from this image that the AlGaN layer has undergone phase-separation, exhibiting bright and dark regions corresponding to Ga- and Al-rich material, respectively. Indeed, closer examination shows that some of the funnels

are filled with phase-separated material. The phase separation occurs here due to the limited incorporation of gallium in the absence of an ammonia overpressure in the MPEC regime and contributes to the roughness of the layer¹⁰. Similar observations have been made in conventionally grown AlGaN material, where phase separation or atomic ordering occurs to accommodate the differences in tetrahedral radii between Al and Ga atoms^{11, 12}.

To gain more insight into the formation of these defects, a range of bare AlN template samples grown at different temperatures were studied. In general, AlN layers grown at lower temperatures (c. 1050° C) exhibited more surface pits in AFM scans compared to those grown at higher temperatures (c. 1100° C). Standard TEM images of such samples are shown in Fig. 3, taken under kinematical diffraction imaging conditions. In the samples studied, hollow nanopipes are observed to open around the depth corresponding to the re-growth interface. In the layer grown at 1140°C [Fig. 3(a)], the majority of these nanopipes are all fully constricted before the surface. However, many nanopipes remain open to the surface of the layer grown at 1060°C [Fig. 3(b)], dilating in the last ~ 50nm to form the funnel-like shape. By imaging in orthogonal $g = (0006)$ and $g = (11-20)$ conditions and using the invisibility criteria, it was determined that the nanopipes and funnels appear to be associated with screw and mixed-type dislocations.

These results clearly indicate that the funnel defects are formed prior to the deposition of the AlGaN layer from nanopipes that are open to the surface of the AlN template. The formation of nanopipes in GaN has been related to the presence of impurities such as oxygen¹³⁻¹⁵, which can be present in MOCVD grown material. This

effect may be greater in AlN due to the increased affinity of Al to oxidize compared to Ga. Indeed, the template may have an oxide layer on its surface (despite cleaning efforts) that acts as an impurity source during re-growth of the template. This would explain why the nanopipes/ funnels all open at a depth corresponding to the nominal re-growth layer thickness in Fig. 3. At the higher bare AlN layer growth temperature, the affinity of Al to oxidize may be reduced and the sticking coefficient of oxygen adatoms is decreased, allowing the impurities to be driven off and the nanopipes to close before the end of growth (Also note the tapering shape of some of the nanopipes in Fig. 3 as the impurities are driven off). At the lower growth temperature, it is the opposite case and the nanopipes remain open to the surface of the layer. Where this occurs, the dilation of the nanopipe at the surface most likely occurs due to a relaxation of the strain field surrounding the dislocation or some kinetic effect related to the presence of impurities on inclined planes¹⁶, forming the funnel shape. It should be noted that this argument suggests growth for longer periods may allow any remaining nanopipes to close off as any remaining impurity sources are exhausted. Indeed, the templates used for the MPEG samples were only re-grown by ~200nm compared to the ~500nm of the bare AlN templates in Fig. 3, increasing the likelihood of observing these funnels.

Any hollow funnels in the template layer are likely to be filled-in during subsequent growth. The dislocation that terminates at the base of the hollow funnel (as this is the effective surface of the template) is then propagated into the epitaxial layer and into the filled funnel. A similar process has been observed for V-pits in InGaN/GaN multi quantum wells (MQWs), where it should be noted that the deformation in the MQW structure leads to localization of charge carriers^{17, 18}. In the case of the MPEG

sample shown in Figs. 1 and 2, the material filling the funnels undergoes phase separation and the path of the dislocation becomes extremely erratic as a result. The presence of the phase-separated material will act to localize carriers within the confines of the funnel. However, dislocations are known to be sites of non-radiative recombination in GaN¹⁹, which would counteract this localization. Lastly, if such funnel defects were to form in a heterostructure, they could act as shortage path in a manner similar to that observed by Hsu *et al* in GaN²⁰.

We examined several AlGaN layers grown by MOCVD in the MPEG regime on AlN templates using TEM techniques. Unusual funnel-like defects were observed in the top of some AlN templates that were filled with Al_xGa_{1-x}N material from the overlying layer. Erratic dislocation paths were formed within some of the funnels in the ~150nm nearest the template surface as a result of phase separation in the ternary AlGaN layer. Studies of bare AlN templates revealed that the funnels were pre-existing hollow defects. We believe that they are formed due to the presence of impurities such as oxygen, which is consistent with the funnels being less common at higher growth temperatures. Our results also indicate that growth for longer periods may reduce the probability that these defects are formed.

Acknowledgements

This work was supported by the Georgia Institute of Technology contract R7776S2 (under the DARPA DUVAP Program Contract FA8718-07-C-0002) through the U.S. Department of Energy under Contract No. DE-AC02-05CH11231 and was

performed at the National Center for Electron Microscopy, Lawrence Berkeley National Laboratory.

References

¹ H. Morkoc, Nitride Semi-Conductors and Devices, Springer-Verlag, Berlin (1999).

² M. A. Khan, M. Shatalov, H. P. Maruska, H. M. Wang, and E. Kuokstis: Jpn. J. Appl. Phys. **44**, 7191 (2005).

³ S. Einfeldt, M. Diesselberg, H. Heinke, D. Hommel, D. Rudloff, J. Christen, and R. F. Davis, J. Appl. Phys. **92**, 118 (2002).

⁴ S. Sumiya, Y. Zhu, J. Zhang, K. Kosaka, M. Miyoshi, T. Shibata, M. Tanaka, and T. Egawa, Jpn. J. Appl. Phys. **47**, 43 (2008).

⁵ C. H. Chen, H. Liu, D. Steigerwald, W. Imler, C. P. Kuo, M. G. Crawford, M. Ludowise, S. Lester, and J. Amano, J. Electron. Mater. **25**, 1004 (1996).

⁶ Y. Ohba and A. Hatano, Jpn. J. Appl. Phys. **35**, L1013 (1996).

⁷ M. Imura, K. Nakano, T. Kitano, N. Fujimoto, N. Okada, K. Balakrishnan, M. Iwaya, S. Kamiyama, H. Amano, I. Akasaki, K. Shimono, T. Noro, T. Takagi, and A. Bandoh, Phys. Stat. Sol. (a) **203**, 1626 (2006).

⁸ J. Han, J. J. Figiel, M. H. Crawford, M. A. Banas, M. E. Bartram, R. M. Biefeld, Y. K. Song, and A. V. Nurmikko, J. Crystal Growth **195**, 291 (1998).

⁹ H. J. Kim, S. Choi, D. Yoo, J.-H. Ryou, R. D. Dupuis, R. F. Dalmau, P. Lu, and Z. Sitar, Appl. Phys. Lett. **93**, 022103 (2008).

¹⁰ H. J. Kim, S. Choi, D. Yoo, J.-H. Ryou, and R. D. Dupuis, J. Crystal Growth **310**, 4880–4884 (2008)

¹¹ A. Wise, R. Nandivada, B. Strawbridge, R. Carpenter, N. Newman, and S. Mahajan, Appl. Phys. Lett. **92**, 261914 (2008).

¹² A.T. Wise, D.-W. Kim, N. Newman and S. Mahajan, Scripta Materialia **54**, 153–157 (2006)

¹³ M. E. Hawkridge and D. Cherns, Appl. Phys. Lett. **87**, 221903 (2005).

¹⁴ I. Arslan and N. D. Browning, Phys. Rev. Lett. **91**, 165501 (2003).

¹⁵ J. Northrup, Phys. Rev. B **73**, 115304 (2006).

¹⁶ Z. Liliental-Weber, Y. Chen, S. Ruvimov and J. Washburn, Phys. Rev. Lett. **79**, 2835 (1997).

¹⁷ Z. Liliental-Weber, J. of Electron Microscopy **49**, 339-348 (2000)

¹⁸ A. Hangleiter, F. Hitzel, C. Netzel, D. Fuhrmann, U. Rossow, G. Ade and P. Hinze, Phys. Rev. Lett. **95**, 127402 (2005).


¹⁹ E. Müller, D. Gerthsen, P. Brückner, F. Scholz, Th. Gruber and A. Waag, Phys. Rev. B **73**, 245316 (2006).

²⁰ J. W. P. Hsu, M. J. Manfra, S. N. G. Chu, C. H. Chen, L. N. Pfeiffer and R. J. Molnar, Appl. Phys. Lett. **78**, 3980 (2001).

Figure 1: (a) Bright field two beam image of AlGaN layer ($x \sim 0.6$) grown by MPEC on AlN template. Erratic dislocation behavior is observed near the top of the template. (b) Kinematical image of the same area showing that the erratic dislocations occur within the boundaries of funnel-like defects. These funnels are filled, as they appear darker in comparison to the surrounding AlN layer.

Figure 2: (a) Z-contrast image of showing the presence of phase-separated material in the AlGaN layer and within the funnels (arrowed).

Figure 3: TEM images taken away from any strongly diffracting condition of AlN layers grown on AlN templates at (a) 1140°C and (b) 1060°C. The arrows mark the approximate position of the interface between the AlN template and regrown AlN. The surface of the 1140°C layer is smooth while the 1060°C sample surface exhibits hollow funnel-like defects that extend several hundreds of nanometers into the layer.



AlGaN

Ga-rich

AlN

500nm



Regrown AlN

(a)



100nm

Regrown AlN

(b)



100nm